





Part	Base Material	Cut	Length	Width	QTY
A	4 x 8 x 1/4"	9.25" x 7.25" Stringer	46.25	35.5	2
B	4 x 8 x 1/4"	6.5" x 18"	6.5	18	1
C	4 x 8 x 1/4"	7.25" x 18"	7.25	18	4
D	4 x 8 x 1/4"	14.5" x 28.5"	14.5	28.5	1
E	2 x 4	9.25"	9.25		6
F	2 x 4	28.5"	28.5		2
G	2 x 4	43.25"	43.25		2
H	2 x 4	34" 38.09deg	34		2
I	2 x 4	17.5"	17.5		3
J	2 x 4	7.75"	7.75		2
K	2 x 2	9.25"	9.25		2
L	2 x 2	15"	15		7
M	2 x 4 x 3/4"	9.25" x 18"	9.25	18	4
N	2 x 4 x 3/4"	9.5" x 18"	9.5	18	1
O	1 x 4	17.25"	17.25		1
P	1 x 4	9.5"	9.5		1
Q	1 x 4	47" 37.08deg	49.75		1
R	Hinges	Purchased			
S	Latch	Purchased			
T	Bed Hook	3D Print			
U	Rail Connector	3D Print			



	Total Length/Area (in/in^2)	# of units	Rounded	Cost Per Unit	Cost
2x4 Length:	335	3.48	4	4	16
1x4 Length:	76.5	0.79	1	4	4
2x2 Length:	123.5	1.28	2	3	6
0.75" Plywood Area	837	0.72	1	48	48
0.25" Plywood Area	4336	0.94	1	30	30
Extras			1	15	15










(x2) Mirror this step









DONE!

